





Auckland Harbour Bridge Contract PSMC003

Resource Consents for Discharge of Abrasive Blast Products 2007 Annual Report



Total Bridge Services
11 Princes Street
Northcote
Auckland, New Zealand
Telephone:+64 9 481 0078
Facsimile:+64 9 481 0079
Date 05 May 2008

Prepared by:







### CONTENTS

1 INTRODUCTION	
2 DISCHARGE TO LAND AND WATER	3
2.1 Location and Extent of Blasting	3
2.2 Abrasive Blasting Products	4
2.3 Contamination Recovery	5
2.4 Surfaces Coated with Lead	5
2.5 Measures undertaken to avoid, remedy, or mitigate any adverse Environmental Effects	5
3 DISCHARGE TO AIR	8
3.1 Details of blasting	8
3.2 Surfaces Coated with Lead	8

Appendix A - Abrasive Blasting Data 2005/2006

Appendix B – Local Resident Survey and Feedback





### 1 INTRODUCTION

This report has been prepared for the Auckland Regional Council in accordance with the special conditions of consent as set out in the Resource Consent for the Auckland Harbour Bridge (AHB). This report covers the period from 1 October 2006 to 30 September 2007.

The Resource Consents have been granted to Transit New Zealand for the discharge of abrasive blasting products from abrasive blasting of the Auckland Harbour Bridge under the following Discharge Permits:

- Discharge Permit No. 23956 for discharge to air
- Discharge Permit No. 23954 for discharge to ground
- Discharge Permit No. 23955 for discharge to water

All conditions of these discharges permits are being complied with. In accordance with the special conditions of consent the following details are discussed:

- The location and extent of blasting, along with details of conditions
- The estimated quantity (in kg) of abrasive blasting products used
- Confirmation of the quantity of contaminants recovered, stored and disposed
- Confirmation that no more than  $10\text{m}^2$  of blasting has been carried out in those areas where lead paint is known to be present
- Conformation that no abrasive blasting has been undertaken on surfaces coated with lead with concentrations greater than 5000 parts per million by weight in the dry film or containing other hazardous air pollutants
- Details of measures undertaken to avoid, remedy, or mitigate any adverse environmental effect
- Details of screens used and the areas where they are deployed
- Details of any complaints received, and their nature

The physical works contractor responsible for the painting of the AHB changed on 1 December 1998 from Serco to Total Bridge Services. The Total Bridge Services contract has a contract period of 10years expiring on 30 November 2008. Total Bridge Services is a joint venture between TBS Farnsworth Limited, Fulton Hogan Limited and Opus International Consultants Limited.





### 2 DISCHARGE TO LAND AND WATER

### 2.1 Location and Extent of Blasting

Over the past twelve months the majority of the abrasive blasting, high pressure water blasting and maintenance painting was carried out on the Original Truss Bridge, on the Overarch, Underarch, at the Northern Viaduct and in the East Extensions. Minor blasting and painting was carried out in Span 5 and Span3 of the Original truss Bridge. Blasting was carried out above sealed public areas at the Northern Viaduct where discharge into the storm water system is possible.

The areas painted include;

- Truss Bridge, Below Walkway, Span 5, Panel Points 0 8;
- East Extension Internal, Boxes 4 -14;
- Overarch remainder completed.
- Southern Viaduct completed except for area over Westhaven drive.

The total quantity of blasting media used over the past 12 months was 54,250kg. This is a reduction compared to the previous years usage (74,675kg).

The maintenance work of the original truss bridge under the walkway in span 5 included the coating of all external steel work from panel points 0-8. This area used a total of 35500kg, which accounted for approximately 65% of all media used in the past 12 months.

The maintenance work of the original truss bridge on the overarch used a total of 9250kg, which accounted for approximately 17% of all media used in the past 12 months.

The maintenance work of the original truss bridge and extensions at the south steel viaduct including coating panels TS01-34 and the equivalent box sections (boxes 74-80). This area used a total of 9500kg, which made up approximately 17% of all media used in the past 12 months.

The East Extension interiors maintenance works includes the recoating of all interior steel work from box 0 to 14. The total volume of blasting media used in this work package was 0kg, this is because abrasive blasting is not used within the Extensions as the paint contains lead. The paint is removed using hand tools (i.e. scrapers) and removed from site at the end of each days work.





### 2.2 Abrasive Blasting Products

Quantity of Abrasive Blasting Products Generated

Details of abrasive blasting carried out on the Auckland Harbour Bridge between 1<sup>st</sup> October 2006 and 30<sup>th</sup> September 2007 have been tabulated and included in Appendix A. For each day the location of the blasting, the work hours, wind speed, wind direction, amounts and type of abrasive, and controls have been recorded. Table 1 below gives the approximate amount of abrasive blasting used in each part of the Bridge over the past 12 months. The period of blasting and prevailing wind direction is also given.

Table 1: Summary of Abrasive Blasting

Location of Blasting	Period	Approximate Amount of Abrasive Used (kg)	Prevailing Wind Direction
Truss Bridge, Span 5, Below Walkway, Panel Point 2 - 3	6/8/7 - 8/8/7	5250	W
Truss Bridge, Span 5, Below Walkway, Panel Point 3 – 4	12/12/9 - 31/8/7	6500	W
Truss Bridge, Span 5, Below Walkway, Panel Point 4 – 5	24/1/7 - 8/2/7	3250	NW
Truss Bridge, Span 5, Below Walkway, Panel Point 5 – 6	18/10/6 - 24/10/6	750	NW
Truss Bridge, Span 5, Below Walkway, Panel Point 6 – 7	22/11/6 – 5/9/	5750	W
Truss Bridge, Span 5, Below Walkway, Panel Point 7 – 8	12/1/7 – 22/9/7	9500	NW/W
Truss Bridge, Overarch	7/6/6 – 28/9/7	9250	W
Southern Viaduct	3/4/7 - 30/9/7	9500	W
East Extension Interiors,	14/9/6 – 7/2/7	0	N/A



### 2.3 Contamination Recovery

In accordance with the conditions of the resource consent it is necessary to minimise the discharge of blast media and paint debris as far as is practicable via capture and correct disposal where discharges are over seawater. Where discharges are over land, all debris is to be captured and removed to an appropriate treatment or disposal facility. It has been found that by adopting a sensible, sympathetic approach to the maintenance operations discharge of contaminants has been kept to a minimum. The most effective method to date has been to restrict blasting to minimum practicable surface areas; i.e. spot blasting the corrosion rather than blasting the whole package, this has been successful in keeping the volume of debris from the old paint systems discharged to less than  $0.05\,\mathrm{m}^3$  per year. Assessments on the environment have shown that the effects from spillage of the coating products to be insignificant under normal working conditions. To date no excessive spills have occurred.

#### 2.4 Surfaces Coated with Lead

#### Areas with Lead Paint Present

On the bridge there are only two locations where lead based paints are present, span 7 and inside the box extensions. Previously it has been estimated that only  $0.051 \, \mathrm{m}^3$  of red lead paint per panel point remains on the bridge.

### Past 12 Months Coatings Operations

In the past 12 months painting of the East Extension Interior has commenced, the present coating on the inner extension is a lead based paint. Because of this the removal of the existing paint is done by the use of hand tools (scrapers etc) and not abrasive blasting, at the completion of each days work the removed paint is collected and disposed of in the appropriate manner.


### **External Coatings Philosophy**

It has been estimated in previous contracts that only a very small fraction of this paint (on average) 5%, or 0.0026m³) is removed by the spot blasting involved in maintenance painting. The adopted philosophy regarding areas contaminated with lead is such that the corrosion will almost certainly reoccur in the same locations. This means that those areas have been blasted in the past thus removing all lead from the surfaces, any further blasting will only take off reapplied paint systems, which do not contain lead. If the area blasted is greater than has been previously cleaned then it has been found that the additional area is minimal.

# 2.5 Measures undertaken to avoid, remedy, or mitigate any adverse Environmental Effects

Total Bridge Services over the past twelve months have continued to as far as practicable avoid, remedy, and mitigate any adverse effects on the environment from the abrasive blasting on the Auckland Harbour Bridge. Methods used include:








- From January 2002 we have exclusively been using more garnet abrasive, this has been instrumental in the reduction of abrasive dust generated whilst blasting. Garnet is more efficient due to its hardness and angular profile and therefore a lesser quantity is used to prepare the steel surfaces compared to basalt and other trailed abrasives.
- High pressure water blasting has continued to be used over the past twelve months to remove as much loose paint, scale and corrosion products from the surfaces as possible before abrasive blasting. Water blasting generates paint flakes rather than generating the dust associated with abrasive blasting. Following the water blasting, sweep blasting is used to obtain a surface profile for anchorage of the paint film.
- Continued development of alternative methods of paint removal. UHP waterblasting (water jetting) up to 30,000 psi has been trialled for paint removal over large flat areas such as the extensions. The main advantage of this system is that dust is minimised, as only a sweep blast is required prior to painting. The major negative impact of this machine is the noise it generates and hence working hours would be slightly reduced so the impact on our neighbours is minimised. The size of the lances used makes this method of preparation unsuitable on the original truss bridge. The option of using UHP as a permanent replacement to abrasive blasting where practicable is still currently under review.
- Surrounding businesses and residents are continually kept informed and updated on information relating to blasting and painting programmes at regular intervals. Quarterly surveys are carried out of the local residents by Total Bridge Services to ensure that over the past twelve months that they were happy with the controls provided, included in the survey was the forward works programme for the remainder of 2007 and 2008. The results are contained in Appendix B.
- Signage was displayed advising motorists and the public of abrasive blasting and coating operations on the Auckland Harbour Bridge.
- The current blasting philosophy is based on spot blasting followed by a light sweep blast. This philosophy together with the high pressure water blasting and ultra high-pressure water blasting where possible minimises the volume of material that is generated. This philosophy has greatly reduced the volume of blasting media used when compared to historical records.
- Long-term solutions are being examined to look at the viability of moving from Moisture Cured Zinc primers to a Thermal Zinc Spray. This is being approached from two different aspects, firstly, in the short-medium term using the thermal zinc spray for spot repairs, and in the long term, complete thermal zinc spraying. Complete Thermal Zinc Spraying is a system that would require the removal of all the existing coating and complete replacement. It has the advantage of reducing the number of spot repairs required, hence the amount of blasting, to a minimum over the foreseeable future. Given the costs associated with this it is







likely that complete removal will be undertaken in various areas as part of the next contract mainly due to the excessive film thicknesses now present on the bridge.





### DISCHARGE TO AIR

As mentioned above the majority of the work carried out between October 2006 and September 2007 occurred on the original truss bridge, on the Overarch, BW span 5, on the southern viaduct and in the East Extension. Details showing the date and time of commencement and duration of dry abrasive blasting and/or spray painting, areas of the bridge being blasted or painted, the type of abrasive used, wind speed and direction, and any control measures undertaken. These details have been tabulated and can be found in Appendix A.

## 3.2 Surfaces Coated with Lead

Over the past twelve months it has been ensured that no blasting has been undertaken on surfaces coated with lead with concentrations greater than 5000 parts per million by weight in the dry film or containing other hazardous air pollutants. As has been mentioned above, corrosion on the bridge occurs repeatedly in the same location meaning the lead paint has been removed in the past.



# APPENDIX A

Abrasive Blasting Data 2006/2007



# October 2006 to September 2007 Weather Database Summary

	to September 2007 Wear			STATE OF THE PARTY OF THE	Aarasiya Tyne A	mount Used Si	creens Used	THE COMME
THE RESIDENCE PUR	ge Weather Conditions	Rain Wind	Directrion	Wind Speed	Abrasive Type   A			
Volk Packa	ge wearner condition				Garnet C	0.75	No	20-3eb 01
		Nil	W	2	Garnet C	1.50	No	27-Sep-07
A	Clear	Nil	SE	4	A STATE OF THE PARTY OF THE PAR	0.50	No	26-Sep-07
Ά	Clear	Nil	S	1	Garnet C	1.25	No	25-Sep-07
/A	Clear	Moderate	N	1	Garnet C	0.75	No	23-Sep-07
ut 6	Overcast	Nil	N	4	Garnet C	1.00	No	22-Sep-07
534	Overcast	Heavy	E	3	Garnet C	1.00	No	21-Sep-07
578	Overcast	Nil	E	8	Garnet C	1.00	No	20-Sep-07
578	Clear		E	7	Garnet C	1.25	No	19-Sep-07
578	Overcast	Light	NE	4	Garnet C		No	18-Sep-07
3578	Clear	Nil	E	5	Garnet C	0.25	No	17-Sep-07
3578	Overcast	Nil	E	1	Garnet C	1.00	No	15-Sep-07
3578	Overcast	Nil	N	1	Garnet C	0.50	No	14-Sep-07
B578	Clear	Nil	W	1	Garnet C	0.75	No	13-Sep-07
B578	Clear	Nil	W	2	Garnet C	0.50		12-Sep-07
B578	Overcast	Nil	The second secon	3	Garnet C	0.75	No	11-Sep-07
	Overcast	Nil	NW	2	Garnet C	1.25	No	10-Sep-0
B578	Clear	Nil	W	4	Garnet C	0.75	No	07-Sep-0
B578	Overcast	Nil	SE	6	Garnet C	0.75	No	06-Sep-0
B578	Overcast	Nil	E	1	Garnet C	0.50	No	00 00
B578	Clear	Nil	SW		- Name and the Party of the Par	0.75	No	05-Sep-0
B578	Oledi		W	0	Garnet C	0.75	No	04-Sep-0
B567	Overcast	Nil	NE NE	0	Garnet C	0.50	No	03-Sep-
B578	Overcast	Nil	SW	8	Garnet C		No	31-Aug-
B523	Overcast	Nil	NW	3	Garnet C	0.50	No	30-Aug-
B534	Clear	Nil	NW	8	Garnet C	0.75	No	29-Aug
B701	Overcast	Nil	NW	7	Garnet C	0.50	No	25-Aug
B578	Overcast	Nil	W	1	Garnet C	0.75	No	24-Aug
B523	Clear	Nil	sw	4	Garnet C		No	23-Aug
B523	Overcast	Nil	W	2	Garnet C	0.75	No	15-Aug
B523	Clear	Nil	E	13	Garnet C		No	14-Aug
B701	Clear	Nil	W	2	Garnet C	1.25	No	13-Aug
B701	Clear	Nil	sW	1	Garnet C	0.75	No	12-Au
B701	Clear	Nil	W	12	Garnet C	1.00	140	
B701	Overcast	Moderate	VV					

# October 2006 to September 2007 Weather Database Summary

TRANSPORTATION PROPERTY.	je   Weather Conditio	ns Rain Wi	nd Directrion	Wind Speed	Abrasive Type	Amount Used	Screens Used	L'ELL-
VOISIEGIE	e weather comme	A CONTRACTOR OF THE PARTY OF TH		NAMES AND PARTY OF THE PARTY OF		1.00	No	11-Aug-07
701	Overcast	Nil	NW	5	Garnet C	0.75	No	10-Aug-07
701	Clear	Nil	W	7	Garnet C	1.25	No	09-Aug-07
623	Overcast	Nil	W	1	Garnet C	0.75	No	08-Aug-07
634	Overcast	Nil	W	4	Garnet C	0.75	No	08-Aug-07
034	Clear	Nil	NW	0	Garnet C	0.50	No	07-Aug-07
1523	Overcast	Light	W	7	Garnet C	0.75	No	06-Aug-07
3523	Overcast	Nil	NW	3	Garnet C	0.25	No	04-Aug-07
	Overcast	Moderate	NW	3	Garnet C	0.50	No	02-Aug-07
3578	Overcast	Nil	W	4	Garnet C	0.50	No	10-Sep-07
3578 3578	Overcast	Nil	NW	4	Garnet C	0.75	No	07-Sep-07
B567	Overcast	Nil	NW	4	Garnet C	1.50	No	06-Sep-07
	Overcast	Nil	W	2	Garnet C	0.50	No	05-Sep-07
B567	Overcast	Nil	SW	1	Garnet C	1.25	No	04-Sep-07
B567	Overcast	Nil	NW	2	Garnet C	0.75	No	08-Feb-07
BW5 4-5	Overcast	Nil	SE	7	Garnet C	1.00	No	07-Feb-07
EXS5	Overcast	Light	SE	6	Garnet C	1.00	No	02-Feb-07
EXN5	Clear	Nil	W	4	Garnet C	1.00	No	01-Feb-07
EXN5	Clear	Nil	NM	1		1.25	No	26-Jan-07
BW54/5	Overcast	Nil	NW	0	Garnet C	0.75	No	25-Jan-0
EXN5	Clear	Nil	NW	1	Garnet C	1.25	No	24-Jan-0
The same between the same of t	Clear	Nil	NM	1	Garnet C	0.75	No	23-Jan-0
BW54/5 EXN6	Clear	Nil	NM	1	Garnet C	0.75	No	22-Jan-0
BW53/4	Clear	Nil	W	1	Garnet C	0.50	No	19-Jan-0
EXN5	Clear	Nil	E	2	Garnet C	0.75	No	18-Jan-0
And the second second second second	Clear	Nil	E	2	Garnet		The state of the s	17.1
EXN5	Oloui		sw	2	Garnet C	0.25	No	17-Jan-0
EXN5	Clear	Nil	W	1	Garnet C	0.50	No	16-Jan-0
EXN5	Clear	Nil	W	1	Garnet C	0.50	No	15-Jan-0
BW53/4	Overcast	Nil	S	5	Garnet C	0.75	No	12-Jan-0
BW57/8	Overcast	Nil	E	1	Garnet C	0.50	No	11-Jan-0
EXN5	Overcast	Nil	SW	5	Garnet C	0.75	No	09-Jan-
EXN5	Overcast	Nil	W	1	Garnet C	0.50	No	12-Dec-0
BW 5 3/4	Clear	Nil	VV					

### October 2006 to September 2007 Weather Database Summary

Work Packet	e   Weather Conditions	Rain	Wind Directrion	Wind Speed	Abrasive Type	Amount Used	Screens Used	Date
halfaril berifad obsiditally bendantinistics.	De la grandina de la companya de la		SW	1	Garnet C	0.50	No	11-Dec-06
3W 5 6/7	Clear	Nil		0	Garnet C	0.75	No	24-Nov-06
BW 5 3/4	Clear	Nil	NW		Garnet C	1.50	No	23-Nov-06
3W 5 3/4	Clear	Nil	NW	0	Garnet C	0.50	No	22-Nov-06
BW 5 6/7	Clear	Nil	NW	0		1.25	No	21-Nov-06
3W 5 3/4	Overcast	Nil	W	1	Garnet C	1.00	No	31-Oct-06
O/A 3 14/15	Overcast	Nil	W	2	Garnet C	1.00	No	26-Oct-06
O/A 3 12/13	Overcast	Nil	W	2	Garnet C	1.25	No	25-Oct-06
O/A 3 12/13	Overcast	Nil	NW	0	Garnet C			24-Oct-06
BW 5 5/6	Overcast	Nil	N	1	Garnet C	0.25	No	19-Oct-06
O/A 3 12/13	Overcast	Nil	NW	3	Garnet C	1.00	No	18-Oct-06
BW 5 5/6	Overcast	Nil	W	3	Garnet C	0.50	No	09-Sep-06
O/A 3 13/14	Overcast	Nil	W	0	Garnet C	0.75	No	04-Oct-06
EXN5	Clear	Nil	SW	2	Garnet C	0.50	No	
EXN5	Clear	Nil	NW	3	Garnet C	0.75	No	21-Sep-06
		Nil	NW	3	Garnet C	1.25	No	20-Sep-06
EXN5	Clear	Nil	NW	1	Garnet C	0.75	No	15-Sep-0
EXN4	Clear	IVII	1444					11.0000
EXN5	Clear	Nil	E	2	Garnet C	0.75	No	14-Sep-0
	Clear	Nil	W	0	Garnet B	0.50	No	12-Sep-0
O/A 3 14/15	Clear	Nil	W	0	Garnet C	0.25	No	07-Jun-0
O/ARCH 3/4	Clear	Nil	W	0	Garnet C	0.50	No	06-Sep-0
O/ARCH	Clear	Nil	Е	5	Garnet C	0.25	No	05-Sep-0




# APPENDIX B

Local Residents Survey and Feedback



AHB LC	CAL RESIDENT FEEDBACK FORM
Date:	26 November 2007
Major work carried out over previous quarter:	Blasting & painting of Span 5 Resurfacing of east extension. Blasting and Painting the Southern Viaduct Upgrade of structural members throughout truss bridge Spill Containment upgrade
Name: Address:	NORTHEOTE POINT. NORTH SHORE
Phone No: \$9(	2)(a)
Do you have any complaints regarding work on the Bridge?	No - Doing. WELL -
Do you feel you are being kept adequately informed when work is undertaken that has an impact on you?	YES.
Suggestions or comments :	HAVE THEY EVER THOUGHT OF PUTTING SPEED RESTRICTION "VISABLE" SIGNS. UNDER BRIDGE, WE GET A FEW IDIOTS THAT THINK ITS A SPEEDWAY NOW PAGAIN, OR LOW JUDGER BANS, MAKE LEOPLE THINK.
Please Contact the folloqueries:	
Date: 29 / //	/ <u>07</u> . 9(2)(a)





AHB LO	OCAL RESIDENT FEEDBACK FORM
Date:	26 November 2007
Major work carried out	Blasting & painting of Span 5
over previous quarter:	Resurfacing of east extension.
	Blasting and Painting the Southern Viaduct
	Upgrade of structural members throughout truss bridge
	Spill Containment upgrade
	s9(2)(a)
Name:	
Address:	
	NORTHCOTE PT.
	AK
Phone No:	s9(2)(a)
Phone No.	
Do you have any	
complaints regarding	No No This Year.
work on the Bridge?	
Do you feel you are	yes. Thank you.
being kept adequately	
informed when work is	
undertaken that has	
an impact on you?	
Suggestions or	Good to have the wire mesh fencing
comments:	exerded above on with
	NOT so much rubbish on front law.
	Thatis
	Alexander and Alexander
	MERRY Ymas + New Yee
Please Contact the follo	owing with any  Jon Patman or Alex Ingram  s9(2)(a)
queries:	
20, 1/2	1, 57
Data: _/ 1 / 1 / 0	V / U /






AHBLO	OCAL RESIDENT FEEDBACK FORM
Date:	26 November 2007
Major work carried out over previous quarter:	Blasting & painting of Span 5 Resurfacing of east extension. Blasting and Painting the Southern Viaduct Upgrade of structural members throughout truss bridge Spill Containment upgrade
Name: Address:	Parsoby Cruising Clyb Inc 141-151 Westhare Only Westhare
Phone No:	s9(2)(a)
Do you have any complaints regarding work on the Bridge?	Only when the Curron Steph-once is chosed to the loss to chive back to them to access Harbor Bridge.
Do you feel you are being kept adequately informed when work is undertaken that has an impact on you?	
Suggestions or comments :	
Please Contact the folloqueries:	owing with any  Jon Patman or Alex Ingram  s9(2)(a)
Date: 50 / 1	






AHB LO	OCAL RESIDENT FEEDBACK FORM
Date:	26 November 2007
Major work carried out over previous quarter:	Blasting & painting of Span 5 Resurfacing of east extension. Blasting and Painting the Southern Viaduct Upgrade of structural members throughout truss bridge Spill Containment upgrade
Name: Address:	s9(2)(a)  NOThcofe Koisi
Phone No:	s9(2)(a)
Do you have any complaints regarding work on the Bridge?	Sanetimes Night crew are noisy
Do you feel you are being kept adequately informed when work is undertaken that has an impact on you?	Yes
Suggestions or comments :	Keep up good wark with graffiti unde Bridge
Please Contact the folloqueries:	Tel: 89(2)(a)
Date: 3 / /2	107






Date:	26 November 2007
Major work carried out over previous quarter:	Blasting & painting of Span 5 Resurfacing of east extension. Blasting and Painting the Southern Viaduct Upgrade of structural members throughout truss bridge Spill Containment upgrade
Name: Address:	9(2)(a) NORTHEOTE, 0627
Phone No:	s9(2)(a)
Do you have any complaints regarding work on the Bridge?	Not At PRESENT
Do you feel you are being kept adequately informed when work is indertaken that has in impact on you?	
peing kept adequately nformed when work is undertaken that has	





	AHB LOC	CAL RESIDENT FE	EDBACK FORM	Λ	
		14 April 2008			
Date: Major Work Ca Out this year :	rried	Painting Span 5 Painting Over-Arch Lanes 1 and 2 Resurface Joint 1 Platform Installa Various Minor Mechan	ation Flat		
Name: Address:		s9(2)(a)			
Phone No:	\$	s9(2)(a)			
Do you have complaints re work on the	egarding	to the proje	to revenue a heat All heis e sand bleshy	he ved abuser course out your upquote.	e s agr
Do you feel y being kept a informed?	you are dequately	if could be of where h	e wenteren	better dieregunin	1 her
Suggestion comments:	or				
Please Con queries:	tact the fo	llowing with any	Jon Patman (Proje Nair Tel	ect Manager) / Sandeep s9(2)(a)	
Date: 2	3 104	108.			






Date:	14 April 2008
Major Work Carried	Painting Span 5
Out this year:	Painting Over-Arch Lanes 1 and 2 Resurfacing
	Loint 1 Platform Installation
	Machanical Projects
	s9(2)(a)
Name:	
Address:	1 to Ma Git
	21-12-6-17
	60(2)(2)
Phone No:	s9(2)(a)
, none , and	
Da way baya any	No - we feel worker are
Do you have any complaints regarding	down their best to minimize advitios
work on the Bridge?	J.
Do you feel you are	Customes relations very good
Do you feel you are	to the contest
being kept adequately	
being kept adequately informed?	hadler apprecias agres
being kept adequately	hadles apprecias agres
being kept adequately	Roalles espression agree
being kept adequately informed?	Would really like to see under thirdege
being kept adequately informed?  Suggestions or	Would really the to see under bridge supply that and dust
being kept adequately informed?	Would really the to see under bridge start of all distance of the total distance of it
being kept adequately informed?  Suggestions or	Would really like to see under trickyle Sweet of Tall alive and dust it  Tand to seed to marrellone if it
being kept adequately informed?  Suggestions or	Would really the to see under bridge surfit of the track to marveline if it actually was sealed of actually was sealed.
being kept adequately informed?  Suggestions or comments:	Would really like to see in de traiclege  Sight of The later and diest  actually was seeded a marvellane of it  actually was seeded and any on the seeded and a s
being kept adequately informed?  Suggestions or	Would really W. I. see under brickyl  Sifeft of Tall dist and dist  Tand to track ke marriellas if it  actually was sealed!)  Dit and dast an anguing was ance

Total Bridge Services Residents Feedback Form QP



AHB LOCAL RESIDENT FEEDBACK FORM		
Date:	14 April 2008	
Major Work Carried Out this year:	Painting Span 5 Painting Over-Arch Lanes 1 and 2 Resurfacing Joint 1 Platform Installation Various Minor Mechanical Projects	
Name: Address:	9(2)(a)	
	NORTHCOTE PT PUCKLOSIA	
Phone No:	() 4805748	
Do you have any complaints regarding work on the Bridge?		
Do you feel you are being kept adequately informed?	Les:	
Suggestions or comments:	Would oprecial your work vehicles Use The road under The bridge Not The dirty part is the middle.  Dist is terrible as cars it house Thank you	
Please Contact the foll queries:	owing with any  Jon Patman (Project Manager) / Sandeep  Nair  Tel:  \$9(2)(a)	
Date: (6 / 04	-, of	





AHB LC	CAL RESIDENT	FEEDBACK FORM
	14 April 2008	en en
Date:	14 April 2000	· · ·
Major Work Carried	Painting Span 5	
out this year:	Painting Over-Arch	
fut tills your.	Lanes 1 and 2 Resurfa	acing
	Joint 1 Platform Insta	llation
	Various Minor Mech	anical Projects
	s9(2)(a)	
Name:	30( <u>2)(</u> 0)	
Address:		
`	Northcite	<del>VIT</del>
	( )s9(2)(a)	
Phone No:		<del></del>
Do you have any	No	
complaints regarding		
work on the Bridge?		
	, (	
Do you feel you are	yes	
being kept adequately		
informed?		
		<i>(</i> 2) 1
Suggestions or	watch 4 c	graffiti
comments:	1/2/ -11	
Commenter		
		Jon Patman (Project Manager) / Sandeep
Please Contact the foll	owing with any	Nair
queries:		Tel: s9(2)(a)
- 1/ 1/1	100	
Date: 16 1 4	100	

