



✗ If centre of headlamp is **above** the black line, illumination is **ineffective**. Bike rack must be raised, or existing headlamps relocated below black line, or an aux lamp fitted.

✓ If centre of headlamp is **below** the black line, illumination is **effective**.