

# PRODUCT SAFETY RECALL

## TRAILPRO Trailers (ALL MODELS)



**Sold at Bunnings from December 2005 to 12 October 2018**

### IDENTIFICATION:

**Trailpro 7x4 Handyman – Model no. TP1 (A-frame drawbar) pictured above**  
Trailpro 500 5X3 – Model no. TP6 (Single drawbar)  
Trailpro Weekender (A-frame drawbar).

**DEFECT:** The trailer's drawbar may break at the front attachment where it bolts to the chassis, leading to failure and detachment of the drawbar. Heavy or frequent commercial use may accelerate this hazard.

**HAZARD:** Detachment of the drawbar poses significant safety hazards to other road users and bystanders.

**WHAT SHOULD CUSTOMERS DO?** All Trailpro trailers have an identification plate on the side of the trailer's drawbar (as shown in the photo). Check to confirm if it's a Trailpro trailer, and if so **stop using the trailer** and contact Bunnings on **0800 561 109**.

**Please Note:** This recall includes other Trailpro trailers subject to a previous recall (November 2018).  
Trailpro 8x4 Tradesman – Model no. TP5 (A-frame drawbar)  
Trailpro 8x5 Tandem – Model no. TP8 (A frame drawbar)

If you have received a Bunnings approved repair on your 8x4 and 8x5 trailer and the serial no. ends with an "R", you are not required to take any further action

If you have any of these trailers, or are in doubt, please contact Bunnings customer service centre on **0800 561 109**. Please note that NZTA-appointed inspectors have been instructed to not issue WoFs on affected models.

For more information, please go to [www.bunnings.co.nz/returns/recalls](http://www.bunnings.co.nz/returns/recalls)  
See [www.recalls.govt.nz](http://www.recalls.govt.nz) for New Zealand product recall information