

Appendices













Appendix A Annotated General Arrangement (GA) Plans


aurecon Kensington Swan NZ TRANSPORT AGENCY 7















Document No. NCI-3PRE-2ENV-RPT-0020 Project No. 250310



















































Appendix B Tree Database

This database in the form of a spreadsheet contains the survey data for the tree survey.

The data is organized by General Arrangement plan sheet.















GA Map Sheet	Tree #	Common name genus / species	Ownership / designation	Largest tree dimensions	Arboricultural value	Photograph in App 4	Comment	Effect of works	Recommendation
1	1	Kanuka	NZTA		М		Kanuka-dominated mass planting	Apparently unaffected by works	
1	2	Mixed native trees	NZTA	2 x 2	М		Kanuka, Karamu, Flax	Apparently unaffected by works	
1	3	Mixed native trees	NZTA	12 x 10	М		See notes	Apparently unaffected by works	
1	4	Kanuka	NZTA	2 x1	L		Small Kanuka and Ti Kouka	Apparently unaffected by works	
1	5	Black wattle	Private	7 x 5	L		Group of black wattle	May be affected by SUP	Remove as necessary
1	6	Black wattle	Private	7 x 5	L		Group of black wattle	In alignment of SUP	Remove
1	7	Cypress	Private	7 x 5	L		Cypress hedge up to 40 stems	Affected by wall construction	Remove
1	8	SEA	Private		н		SEA designation west of motorway	Apparently unaffected by works	
1	9	Lucas Creek			н		See note for 1.3	Apparently unaffected by works	
1	10	Mixed amenity planting	AT/NZTA	4 x 4	М		Mixed amenity planting see notes	Mostly unaffected	Remove as necessary
1	11	Mixed amenity planting	AT	1 x 1	L		Small areas of bedding plants	Affected by busway bridge and approach	Remove
1	12	Mixed amenity planting	AT	3 x 3	М		See notes	Affected by alterations to busway	Remove as necessary
2	1	Black Wattle	NZTA	3 x 3	L		Weed	Stands in busway	Remove
2	2	Mixed native planting	NZTA	3 x 3	L		Ti Kouka and Kanuka around pond	Stands in SUP and busway	Remove as necessary
2	3	Kohuhu hedge	NZTA	4 x 4	L		Hedge along fence	Stands between SUP and busway	Remove
2	4	Flax and Ti Kouka	NZTA	1 x 1	L		Ornamental shrubs	Close to civils works	Remove
2	5	Mixed native planting	NZTA	4 x 4	М		See notes	In Busway, affected by batter	Remove






2 Black wattle and macrocarpa 10 x 8 Μ See notes Affected by SUP ramp, excavations 6 Private Remove as necessary 2 7 Kohuhu hedge NZTA 3 x 2 Μ Screening hedge Between Busway and SUP Remove 2 Kohuhu hedge NZTA 3 x 2 Affected by batter / SUP Remove as necessary 8 Μ Screening hedge 2 9 Kohuhu hedge NZTA 3 x 2 Μ Screening hedge Between Busway and SUP Remove 2 Mixed native planting NZTA 10 5 x 4 Μ Mixed amenity planting Appears unaffected by works Remove as necessary 2 Flax and Ti Kouka NZTA **Ornamental planting** 11 1 x 1 L May be affected by wetland construction Remove as necessary 2 Μ Three radiata pines 12 Radiata pine Private 10 x 8 May be affected by wetland construction Remove as necessary Some may be affected by wetland 2 13 Radiata pine Private 12 x 8 Μ Group of up to 16 radiata pines construction Remove as necessary 2 May be affected by excavation 14 Black wattle and weeds Private 5 x 5 L Exotic weeds Remove as necessary 3 Dead 1 3 2 Flax and small shrubs NZTA 1 x 1 L Flax planted around SW pond Affected by SUP and busway Remove Wattle standing on boundary of Spencer Road 3 3 Black wattle Private 7 x 7 Affected by SUP and busway Remove L development 3 4 Gone 3 Mixed Pine and Gum windrow AT 12 x 8 Μ Windrow planting 5 Apparently unaffected by works 3 6 Yunnan poplar and Pine NZTA / Private 5 x 4 L Amenity planting adjacent to roading works Apparently unaffected by works Remove as necessary 3 7 Ngaio / Ti Kouka / Flax Park 4 x 4 L Amenity planting along fence. Low value Between Busway and enforcement bay Remove as necessary 3 NZTA Isolated tree 8 Pohutukawa 4 x 4 L Apparently unaffected by works 3 9 Μ See notes Native group Private 6 x 4 Construction yard Remove as necessary Isolate and retain if 3 Private / NZTA 10 x 8 Μ possible 10 Slash Pine group See notes Construction yard 4 Mixed amenity planting Park 4 x 4 See notes Affected by SUP and Busway L Remove as necessary 1 See 4.1 of main report 4 2 Rough hedge Park 4 x 4 L Affected by SUP and Busway Remove Park 10 x 8 4 3 Mixed planting L See 4.1 of main report Affected by bored pile wall Remove as necessary 4 4 Mixed planting Park 8 x 6 Μ See 4.1 of main report Affected by wall Remove as necessary Park L See 4.1 of main report 4 5 Mixed planting 4 x 4 Affected by excavation Remove as necessary 4 Conifer hedge Private 3 x 1 Μ Conifer hedge in very poor health Affected by SUP ramp Remove

add add and a start a



6




and also and a





6 5 Flax x 50 60 NZTA 1 x 1 M Mass planting of Harakele footprint Remove an exclusion 6 6 Washingtonia Palmx x 6 NZTA 7 x 2 M Remove an exclusion Apparently unaffected by SUP works Remove an exclusion 6 7 Pohutukawa x 8 NZTA 5 x 5 M Group of Pohutukawa and other native Party affected by SUP works Remove an exclusion 6 10 Mieed native planting NZTA 8 x 4 M Trees of small overall sture Party affected by SUP works Remove an exclusion 6 10 Mised native planting NZTA 4 x 4 M Trees of small overall sture Party affected by SUP works Remove an exclusion 6 10 Mass planting of flax NZTA 4 x 4 M Trees of small overall sture Party affected by sup works Remove an exclusion 6 11 Mass planting of flax NZTA 4 x 4 M Sec of oup of Kanuka Apprently unaffected by works Remove an exclusion 6 13 Mixela native windrow Parts NZTA 5 x 5 M Sec of	6	4	12 x Ngaio	NZTA	4 x 4	Μ	Row of about 12 Ngaio bushes	Within busway footprint	Remove
6 7 Polutukawa x 8 NZTA 5 x 5 M Group of Polutukawa and other natives Parity affected by SUP works Remove 6 8 Mixed native planting NZTA/AT 4 x 4 M Trees of small overall stature Parity affected by SUP works Remove as nece 6 9 Queen Palm x 8 NZTA 8 x 4 M Trees of small overall stature Parity affected by works Remove as nece 6 10 Mixed native planting NZTA 4 x 4 M Trees of small overall stature Parity affected by works Remove as nece 6 10 Mixed native planting NZTA 4 x 4 M Trees of small overall stature Parity affected by works Remove as nece 6 13 Mass planting of flax NZTA 1 x 1 M Mass planting on Harakeke Apparently unaffected by works Remove as nece 6 13 Kanuka x 8 NZTA 9 x 5 M See notes Affected by bridge widening Remove as nece 6 16 Fick and Washingtonia Palm NZTA 5 x 2 M Flas groundcover and 6 Washingtonia Palms Aff	6	5	Flax x 50-60	NZTA	1 x 1	М	Mass planting of Harakeke	Partly within excavation / construction footprint	Remove as necessary
6 8 Mixed native planting NZTA/AT 4 x 4 M Trees of small overall stature Partly affected by SUP and busway works Remove as need 6 9 Queen Palm x 8 NZTA 8 x 4 M Trees of small overall stature Partly affected by SUP and busway works Remove as need 6 10 Mixed native planting NZTA 4 x 4 M Trees of small overall stature Partly affected by works Remove as need 6 11 Mass planting of flax NZTA 1 x 1 M Mass planting of Harakeke Apparently unaffected by works Remove as need 6 12 Washingtonia Palm x 6 NZTA 7 x 2 M Group of Kanuka Affected by excavation Remove as need 6 13 Kanuka x 8 NZTA 4 x 3 M Group of Kanuka Affected by excavation Remove as need 6 15 Mixed native planting NZTA 9 x 5 M See notes Affected by works and xcavation Remove as need 6 15 Mixed native planting on Palm NZTA 8 x 3 M See notes Affected by cavavis and xcavati	6	6	Washingtonia Palm x 6	NZTA	7 x 2	М	Row of Washingtonia Palms	Apparently unaffected by works	
6 9 Queen Palm x 8 NZTA 8 x 4 M Palms and shrubs Apparently unaffected by works 6 10 Mixed native planting NZTA 4 x 4 M Trees of small overall stature. Parity affected by busway and construction Remove as nece 6 11 Mass planting of flax NZTA 1 x 1 M Mass planting of Harakeke Apparently unaffected by works 6 12 Washingtonia Palm x 6 NZTA 7 x 2 M Mass planting of Kanuka Apparently unaffected by works 6 13 Kanuka x 8 NZTA 4 x 3 M Group of Kanuka Apparently unaffected by excavation Remove as nece 6 13 Kanuka x 8 NZTA 9 x 5 M See notes Affected by earthworks Remove as nece 6 15 Flax and Washingtonia Palm NZTA 5 x 2 M Elas groundcover and 6 Washingtonia Palms Affected by ondow sind excavation Remove as nece 6 16 Flax and Washingtonia Palm NZTA 5 x 2 M See notes Affected by conducits and excavation Remove as nece 6	6	7	Pohutukawa x 8	NZTA	5 x 5	М	Group of Pohutukawa and other natives	Partly affected by SUP works	Remove
6 10 Mixed native planting NZTA 4 x 4 M Trees of small overall stature Partly affected by busy and construction Remove as need 6 11 Mass planting of flax NZTA 1 x 1 M Mass planting of Harakeke Apparently unaffected by works 6 12 Washingtonia Palm x 6 NZTA 7 x 2 M Row of Washingtonia Palms Apparently unaffected by works 6 13 Kanuka x 8 NZTA 4 x 3 M Group of Kanuka Affected by excavation Remove as need 6 14 Mixed native windrow Parks / WWTP 9 x 9 M See 4.3 of main report May be affected by excavation Remove as need 6 15 Mixed native planting NZTA 9 x 5 M See notes Affected by bridge widening Remove as need 6 16 Iax and Washingtonia Palm NZTA 8 x 2 M Flax groundcover and 6 Washingtonia Palms Affected by bridge widening Remove as need 6 16 Iax and Washingtonia NZTA 7 x 7 M See notes Affected by cavation Remove as need 6<	6	8	Mixed native planting	NZTA/AT	4 x 4	Μ	 Trees of small overall stature	Partly affected by SUP and busway works	Remove as necessary
6 11 Mass planting of flax NZTA 1 x 1 M Mass planting of Harakeke Apparently unaffected by works 6 12 Washingtonia Palm x 6 NZTA 7 x 2 M Row of Washingtonia Palms Apparently unaffected by works 6 13 Kanuka x 8 NZTA 4 x 3 M Group of Kanuka Affected by excavation Remove 6 14 Mixed native windrow Parks / WWTP 9 x 9 M See 4.3 of main report May be affected by excavation Remove as nece 6 16 Flax and Washingtonia Palm NZTA 5 x 2 M Eas proundcover and 6 Washingtonia Palms Affected by bridge widening Remove as nece 6 17 Flax and Washingtonia Palm NZTA 5 x 2 M Eas proundcover and 6 Washingtonia Palms Affected by bridge widening Remove as nece 6 17 Flax and Washingtonia NZTA 7 x 7 M See notes Affected by roadworks and excavation Remove as nece 6 18 Ngiao, Pohutukawa NZTA 7 x 7 M See notes May be affected by SUP works Remove as nece	6	9	Queen Palm x 8	NZTA	8 x 4	М	Palms and shrubs	Apparently unaffected by works	
6 12 Washingtonia Palm x 6 NZTA 7 x 2 M Row of Washingtonia Palms Apparently unaffected by works 6 13 Kanuka x 8 NZTA 4 x 3 M Group of Kanuka Affected by excavation Remove 6 14 Mixed native windrow Parks / WWTP 9 x 9 M See 4.3 of main report May be affected by excavation Remove as nece 6 15 Mixed native planting NZTA 9 x 5 M See notes Affected by excavation Remove as nece 6 16 Flax and Washingtonia Palm NZTA 5 x 2 M Eax groundcover and 6 Washingtonia Palms Affected by bridge widening Remove as nece 6 17 Flax and Washingtonia Palm NZTA 5 x 2 M Eax groundcover and 6 Washingtonia Palms Affected by bridge widening Remove as nece 6 18 Ngalo, Pohutukawa NZTA 4 x 4 M See notes Affected by raadworks and excavation Remove as nece 6 18 Ngalo, Pohutukawa NZTA 7 x 7 M See notes May be affected by SUP works Remove as nece </td <td>6</td> <td>10</td> <td>Mixed native planting</td> <td>NZTA</td> <td>4 x 4</td> <td>М</td> <td>Trees of small overall stature</td> <td>Partly affected by busway and construction</td> <td>Remove as necessary</td>	6	10	Mixed native planting	NZTA	4 x 4	М	Trees of small overall stature	Partly affected by busway and construction	Remove as necessary
6 13 Kanuka x 8 NZTA 4 x 3 M Group of Kanuka Affected by excavation Remove 6 14 Mixed native windrow Parks / WWTP 9 x 9 M See 4.3 of main report May be affected by excavation Remove an ecc 6 15 Mixed native planting NZTA 9 x 5 M See notes Affected by exclusion Remove an ecc 6 16 Flax and Washingtonia Palm NZTA 5 x 2 M Flax groundcover and 6 Washingtonia Palm Affected by bridge widening Remove an ecc 6 17 Flax and Washingtonia Palm NZTA 8 x 3 M See notes Affected by bridge widening Remove an ecc 6 18 Ngaio, Pohutukawa NZTA 8 x 3 M See notes Affected by roadworks and excavation Remove an ecc 6 18 Ngaio, Pohutukawa NZTA 7 x 7 M See notes May be affected by SUP works Remove an ecc 7 Pohutukawa x 12 AT 5 x 5 M See notes May be affected by SUP works Remove an ecc 8 3	6	11	Mass planting of flax	NZTA	1 x 1	М	Mass planting of Harakeke	Apparently unaffected by works	
614Mixed native windrowParks / WWTP9 × 9MSee A.3 of main reportMay be affected by excavationRemove as needed615Mixed native plantingNZTA9 × 5MSee notesAffected by each worksRemove as needed616Flax and Washingtonia PalmNZTA5 × 2MFlax groundcover and 6 Washingtonia PalmsAffected by bridge wideningRemove as needed617Flax and Washingtonia PalmNZTA8 × 3MFlax groundcover and 6 Washingtonia PalmsAffected by bridge wideningRemove as needed618Ngaio, PohutukawaNZTA4 × 4MSee notesAffected by roadworks and excavationRemove as needed62020 × KanukaNZTA7 × 7MSee notesMay be affected by SUP worksRemove as needed621PohutukawaNZTA3 × 2LSee notesMay be affected by SUP worksRemove as needed81Kanuka x 20AT5 × 5MSee notesMay be affected by SUP worksRemove as needed83Road reserve treesAT5 × 5MSee notesMay be affected by SUP worksRemove as needed83Road reserve treesAT5 × 5MSee notesMay be affected by SUP worksRemove as needed84Kanuka x 15AT5 × 5MSee notesMay be affected by sup worksRemove as needed85Washingtonia Palm x 22	6	12	Washingtonia Palm x 6	NZTA	7 x 2	М	Row of Washingtonia Palms	Apparently unaffected by works	
615Mixed native plantingNZTA9 x 5MSee notesAffected by carthworksRemove as notes616Flax and Washingtonia PalmNZTA5 x 2MFlax groundcover and 6 Washingtonia PalmsAffected by bridge wideningRemove as notes617Flax and Washingtonia PalmNZTA8 x 3MFlax groundcover and 6 Washingtonia PalmsAffected by bridge wideningRemove as notes618Ngaio, PohutukawaNZTA4 x 4MSee notesAffected by roadworks and excavationRemove as notes62020 x KanukaNZTA7 x 7MSee notesMal be affected by SUP worksRemove as notes621PohutukawaNZTA5 x 5MSee notesMal be affected by SUP worksRemove as notes81Kanuka x 20AT5 x 5MSee notesMal be affected by SUP worksRemove as notes83Road reserve treesAT5 x 5MSee notesMal be affected by SUP worksRemove as notes84Kanuka x 15AT5 x 5MSee notesMal be affected by SUP worksRemove as notes85Washingtonia Palm x 22AT5 x 5MSee notesMal be affected by SUP worksRemove as notes84Kanuka x 15AT5 x 5MSee notesMal be affected by SUP worksRemove as notes85Washingtonia Palm x 22AT5 x 5MSee A	6	13	Kanuka x 8	NZTA	4 x 3	М	Group of Kanuka	Affected by excavation	Remove
616Flax and Washingtonia PalmNZTA5 x 2MFlax groundcover and 6 Washingtonia PalmsAffected by bridge wideningRemove as need617Flax and Washingtonia PalmNZTA8 x 3MFlax groundcover and 6 Washingtonia PalmsAffected by bridge wideningRemove as need618Ngaio, PohutukawaNZTA4 x 4MSee notesAffected by roadworks and excavationRemove as need62020 x KanukaNZTA7 x 7MSee notesMay be affected by SUP worksRemove as need621PohutukawaNZTA3 x 2LSmall road berm treesMay be affected by SUP worksRemove as need81Kanuka x 20AT5 x 5MSee notesMay be affected by SUP worksRemove as need82Pohutukawa x 12AT5 x 5MSee notesMay be affected by SUP worksRemove as need83Road reserve treesAT5 x 5MSee notesMay be affected by SUP worksRemove as need84Kanuka x 15AT5 x 5MSee notesMay be affected by SUP worksRemove as need85Washingtonia Palm x 22AT5 x 5MSee notesMay be affected by excavationRemove as need86Pohutukawa x 9AT4 x 2LRow of small hushy KanukaMay be affected by sup worksRemove as need87Pohutukawa x 9AT4 x 2L	6	14	Mixed native windrow	Parks / WWTP	9 x 9	М	See 4.3 of main report	May be affected by excavation	Remove as necessary
And ControlNote of the control <td>6</td> <td>15</td> <td>Mixed native planting</td> <td>NZTA</td> <td>9 x 5</td> <td>М</td> <td>See notes</td> <td>Affected by earthworks</td> <td>Remove as necessary</td>	6	15	Mixed native planting	NZTA	9 x 5	М	See notes	Affected by earthworks	Remove as necessary
618Ngaio, PohutukawaNZTA4 x 4MSee notesAffected by rodworks and excavationRemove as notes62020 x KanukaNZTA7 x 7MSee notesMay be affected by SUP worksRemove as notes621PohutukawaNZTA3 x 2LSmall road berm treesMay be affected by excavationRemove as notes81Kanuka x 20AT5 x 5MSee notesMay be affected by SUP worksRemove as notes82Pohutukawa x 12AT5 x 5MSee notesMay be affected by SUP worksRemove as notes83Road reserve treesAT5 x 5MSee notesMay be affected by SUP worksRemove as notes84Kanuka x 15AT5 x 5MSee notesMay be affected by SUP worksRemove as notes85Washingtonia Palm x 22AT5 x 5MSee 4.5 of main reportMore comment in main reportRemove as notes86Pohutukawa x 9AT5 x 2MRew of small, bushy KanukaMay be affected by new intersection worksRemove87Pohutukawa and NgaioAT5 x 5MSee notesMay be affected by SUP worksRemove as notes88Mixed native plantingParks / WWTP9 x 9HSee 0.3 of main reportMore comment in main reportRemove as notes88Mixed native plantingParks / WWTP9 x 9HSee 0.3 o	6	16	Flax and Washingtonia Palm	NZTA	5 x 2	М	Flax groundcover and 6 Washingtonia Palms	Affected by bridge widening	Remove as necessary
62020 x KanukaNZTA7 x 7MSee notesMay be affected by SUP worksRemove as nece621PohutukawaNZTA3 x 2LSmall road berm treesMay be affected by excavationRemove as nece81Kanuka x 20AT5 x 5MSee notesMay be affected by SUP worksRemove as nece82Pohutukawa x 12AT5 x 5MSee notesMay be affected by SUP worksRemove as nece83Road reserve treesAT5 x 5MSee 4.5 of main reportMore comment in main reportRemove as nece84Kanuka x 15AT3 x 2LRow of small, bushy KanukaMay be affected by excavationRemove as nece85Washingtonia Palm x 22AT5 x 2MRemove of small, bushy KanukaMay be affected by excavationRemove as nece86Pohutukawa x 9AT4 x 2LRow of small PohutukawaWill be affected by new intersection worksRemove as nece87Pohutukawa and NgaioAT5 x 5MSee notesMay be affected by SUP worksRemove as nece87Pohutukawa and NgaioAT5 x 5MSee notesMay be affected by SUP worksRemove as nece87Pohutukawa and NgaioAT5 x 5MSee notesMay be affected by SUP worksRemove as nece88Nixed native plantingParks / WWTP9 x 9HSee	6	17	Flax and Washingtonia Palm	NZTA	8 x 3	М	Flax groundcover and 6 Washingtonia Palms	Affected by bridge widening	Remove as necessary
621PohutukawaNZTA3 x 2LSmall road berm treesMay be affected by excavationRemove as nece81Kanuka x 20AT5 x 5MSee notesMay be affected by SUP worksRemove as nece82Pohutukawa x 12AT5 x 5MSmall road berm treesMay be affected by SUP worksRemove as nece83Road reserve treesAT5 x 5MSee 4.5 of main reportMore comment in main reportRemove as nece84Kanuka x 15AT3 x 2LRow of small, bushy KanukaMay be affected by excavationRemove as nece85Washingtonia Palm x 22AT5 x 2MRow of small, bushy KanukaMay be affected by new intersection worksRemove as nece86Pohutukawa x 9AT4 x 2LRow of small PohutukawaWithin roading footprintRemove as nece87Pohutukawa and NgaioAT5 x 5MSee notesMay be affected by SUP worksRemove as nece88Mixed native plantingParks / WWTP9 x 9HSee notesMay be affected by new intersection worksRemove as nece88Mixed native plantingParks / WWTP9 x 9HSee notesSee notesMay be affected by SUP worksRemove as nece88Mixed native plantingParks / WWTP9 x 9HSee notesSee notesSee notesSee notes for 6/15 above	6	18	Ngaio, Pohutukawa	NZTA	4 x 4	М	See notes	Affected by roadworks and excavation	Remove as necessary
8 1 Kanuka x 20 AT 5 x 5 M See notes May be affected by SUP works Remove as nece 8 2 Pohutukawa x 12 AT 5 x 5 M Small road berm trees May be affected by SUP works Remove as nece 8 3 Road reserve trees AT 5 x 5 M See notes May be affected by SUP works Remove as nece 8 4 Kanuka x 15 AT 5 x 5 M See 4.5 of main report More comment in main report Remove as nece 8 4 Kanuka x 15 AT 5 x 2 L Row of small, bushy Kanuka May be affected by new intersection works Remove as nece 8 5 Washingtonia Palm x 22 AT 5 x 2 M Row of small, bushy Kanuka May be affected by new intersection works Remove as nece 8 6 Pohutukawa x 9 AT 4 x 2 L Row of small Pohutukawa Within roading footprint Remove as nece 8 7 Pohutukawa and Ngaio AT 5 x 5 M See notes May be affected by SUP works Remove as nece 8	6	20	20 x Kanuka	NZTA	7 x 7	М	See notes	May be affected by SUP works	Remove as necessary
82Pohutukawa x 12AT5 x 5MSmall road berm treesMay be affected by SUP worksRemove as nece83Road reserve treesAT5 x 5MSee 4.5 of main reportMore comment in main reportRemove as nece84Kanuka x 15AT3 x 2LRow of small, bushy KanukaMay be affected by excavationRemove as nece85Washingtonia Palm x 22AT5 x 2MRow of small, bushy KanukaWill be affected by new intersection worksRemove as nece86Pohutukawa x 9AT5 x 5MRow of small PohutukawaWithin roading footprintRemove as nece87Pohutukawa and NgaioAT5 x 5MSee notesMay be affected by SUP worksRemove as nece88Mixed native plantingParks / WWTP9 x 9HSee 4.3 of main reportSee notes for 6/15 above	6	21	Pohutukawa	NZTA	3 x 2	L	Small road berm trees	May be affected by excavation	Remove as necessary
8 3 Road reserve trees AT 5 x 5 M See 4.5 of main report More comment in main report Remove as neces 8 4 Kanuka x 15 AT 3 x 2 L Row of small, bushy Kanuka May be affected by excavation Remove as neces 8 5 Washingtonia Palm x 22 AT 5 x 2 M Row of small Washingtonia Palms Will be affected by new intersection works Remove as neces 8 6 Pohutukawa x 9 AT 4 x 2 L Row of small Pohutukawa Within roading footprint Remove as neces 8 7 Pohutukawa and Ngaio AT 5 x 5 M See notes May be affected by SUP works Remove as neces 8 8 Mixed native planting Parks / WWTP 9 x 9 H See notes May be affected by SUP works Remove as neces	8	1	Kanuka x 20	AT	5 x 5	М	See notes	May be affected by SUP works	Remove as necessary
8 4 Kanuka x 15 AT 3 x 2 L Row of small, bushy Kanuka May be affected by excavation Remove as necessary 8 5 Washingtonia Palm x 22 AT 5 x 2 M Row of small, bushy Kanuka Will be affected by new intersection works Remove as necessary 8 6 Pohutukawa x 9 AT 4 x 2 L Row of small Pohutukawa Within roading footprint Remove as necessary 8 7 Pohutukawa and Ngaio AT 5 x 5 M See notes May be affected by SUP works Remove as necessary 8 8 Mixed native planting Parks / WWTP 9 x 9 H See 4.3 of main report See notes for 6/15 above	8	2	Pohutukawa x 12	AT	5 x 5	М	Small road berm trees	May be affected by SUP works	Remove as necessary
8 5 Washingtonia Palm x 22 AT 5 x 2 M Row of small Washingtonia Palms Will be affected by new intersection works Remove 8 6 Pohutukawa x 9 AT 4 x 2 L Row of small Pohutukawa Will be affected by new intersection works Remove 8 7 Pohutukawa and Ngaio AT 5 x 5 M See notes May be affected by SUP works Remove as needed 8 8 Mixed native planting Parks / WWTP 9 x 9 H See 4.3 of main report See notes for 6/15 above	8	3	Road reserve trees	AT	5 x 5	М	See 4.5 of main report	More comment in main report	Remove as necessary
8 6 Pohutukawa x 9 AT 4 x 2 L Row of small Pohutukawa Within roading footprint Remove 8 7 Pohutukawa and Ngaio AT 5 x 5 M See notes May be affected by SUP works Remove as nece 8 8 Mixed native planting Parks / WWTP 9 x 9 H See 4.3 of main report See notes for 6/15 above	8	4	Kanuka x 15	AT	3 x 2	L	Row of small, bushy Kanuka	May be affected by excavation	Remove as necessary
8 7 Pohutukawa and Ngaio AT 5 x 5 M See notes May be affected by SUP works Remove as nece 8 8 Mixed native planting Parks / WWTP 9 x 9 H See 4.3 of main report See notes for 6/15 above	8	5	Washingtonia Palm x 22	AT	5 x 2	М	Row of small Washingtonia Palms	Will be affected by new intersection works	Remove
8 8 Mixed native planting Parks / WWTP 9 x 9 H See 4.3 of main report See notes for 6/15 above	8	6	Pohutukawa x 9	AT	4 x 2	L	Row of small Pohutukawa	Within roading footprint	Remove
	8	7	Pohutukawa and Ngaio	AT	5 x 5	М	See notes	May be affected by SUP works	Remove as necessary
8 9 Mixed native planting WWTP 7 x 7 M See 4.4 of main report will be affected by roundabout works Remove as nece	8	8	Mixed native planting	Parks / WWTP	9 x 9	н	 See 4.3 of main report	See notes for 6/15 above	
	8	9	Mixed native planting	WWTP	7 x 7	М	See 4.4 of main report	will be affected by roundabout works	Remove as necessary




ad a have and a



Appendix C Notes to Annotated GA plans















This data consists of additional explanatory or descriptive notes about trees in **Appendix B.** Many of the groups described here in **Appendix C** are also described in more detail in Section 4 of the main report. The notes below are organized by General Arrangement plan sheet (i.e. 1.3 refers to Tree 3 on GA sheet 1).

Sheet 1

- 1.3 Area of dense, healthy native trees with heights up to 12m. Species include Rimu, Kahikatea and many Kanuka trees with understorey species such as Ponga, Karamu and Hangehange. A new SW connection is proposed to Lucas Creek, within the NZTA designation, so no vegetation is protected. Works will need to be carefully executed to avoid unnecessary damage to riparian vegetation.
- 1.10 Mixed amenity planting between busway carpark and SH1. Most planting is within the NZTA designation and consists of trees up to 4m in height and spread. Species include Magnolia, Karamu, Ti Kouka, Manuka, Houhere, Kohuhu, Mapou, Karo, Puriri, and Tanekaha. The plantings are affected where the busway bridge crosses over the motorway where it is assumed approach works will be required.
- 1.12 Area of general amenity planting within bus station designation that may affected by busway alterations and wall construction. Bushes and small trees up to 3m in height, includes Karamu, Kanuka, Ti Kouka, Harakeke and various grasses. Not protected due to small size. To be removed as necessary mitigation by replacement planting.

Sheet 2

- 2.5 An area of mixed native planting up to 4 x 4m. Consists of commonly-planted native species such as Kanuka / Manuka, Ti Kouka, Harakeke, Kohuhu, Karamu. This area will be within the footprint of SUP and busway and is affected by the excavation of battered slopes. Areas of planting will need to be removed to facilitate civil works.
- 2.6 Four Black Wattle trees and a Macrocarpa standing in open ground. The Macrocarpa and up to three of the Wattle trees will be affected by adjacent civils work, requiring removal. Although these trees are larger than the mixed planting adjacent, they are not of great arboricultural significance. The trees appear to stand on private property but are not protected by the AUP.

Sheet 3

- 3.9 Two small islands of native trees up to 6m in height Ti Kouka x 6 and Karamu, Mapou and Karo. The trees are isolated and have little amenity impact. Removal may be necessary if the area is to be used as a construction yard.
- 3.10 A planting of Slash Pine (*Pinus elliotti*) 30+ trees with some landscape value. The undergrowth is gorse, Ponga, Mahoe and Manuka. The area is designated as construction yard, but is unlikely to be used for this purpose. The trees collectively have some landscape value.

Sheet 4

4.1 An area of bush within the landfill site within the NZTA designation. The vegetation consists of mixed amenity planting and natural recruitment consisting of small natives and a scattering of exotics of dimensions up to 4 x 4m. Natives include Ngaio, Harakeke, Karamu, and Western Red Cedar, Karo as well as wattle and gorse. This area has no specific theme and the plantings are not of high individual value. Part of this area must be cleared to accommodate the busway and SUP.

aurecon KensingtonSwan





Sheet 5

- 5.3 A row of 12 x Ti Kouka close to the existing road edge, and a row of about 10 small Kanuka along the fence line. Will need to be cleared to accommodate roading works.
- 5.4 This group has a double or single row of 25 x Queen Palm (Syagrus romanzoffiana) up to about 10m tall at the northern end. The palm trees have some amenity value and may be suitable for relocation. The palms give way to a Kanuka hedge along the fence line to the south. There is also a small group of Ti Kouka. All of these trees will have to be removed as they stand within the footprint of construction works.
- 5.7 A group of mixed native and exotic trees. The most prominent are 4 x Silky Oak (*Grevillea robusta*) with the rest an eclectic mix of native (e.g. Puriri, Puka and Rewarewa) and exotic (Tobacco Weed (*Solanum mauritianum*), Magnolia, and *Syzigium*), amongst others. The trees provide some screening and have moderate amenity value. This group is located on private land just outside the NZTA designation except for an island of Harakeke at the northern end, which is closer to the existing roadway. It appears that the bank on which the trees stand may be undercut by road widening works. The trees are not protected.
- 5.8 A group of about 10 Ti Kouka up to 5m in height standing on NZTA land inside the fence with the WWTP. There are also three smaller Ti Kouka and a number of Brush Wattle (*Paraserianthes lopantha*) in the boundary fence.
- 5.9 A double row of Queen Palm (*Syagrus romanzoffiana*) up to 10m in height standing on NZTA land. The trees are within the roading footprint and need to be removed. These trees may be suitable for relocation.
- 5.10 Two clusters of mixed native planting up to 6m in height including Puka, Pohutukawa, Kanuka, Totara as well as privet. All trees between the motorway and the WWTP ponds are proposed to be removed due to road widening works here.
- 5.14 An overgrown area of small native planting including small Manuka / Kanuka bushes and Pohutukawa, together with flax and shrubs. Amenity value is low. Will be removed as part of busway excavations.

Sheet 6

- 6.15 This planting consists of small native trees such as Ngaio and Pohutukawa within the NZTA designation and inside the motorway reserve fence. The largest trees are at the southern end of the group close to the intersection between SH18 and SH1 and are up to 6m in height. The trees are scattered and variable, giving them little visual bulk and only moderate amenity value at best. The bank on which the trees stand will be affected by earthworks, requiring the removal of the trees.
- 6.18 Roadside planting of Ngaio, Pohutukawa and other small trees up to 6 x 6m in size, growing west of the motorway. This area will be affected by SUP works as well as excavation for road works, and some of the trees may have to be removed. The trees are individually of low to moderate arboricultural value.
- 6.20 A row of about 20 Kanuka trees up to 7 x 7m in size, and one self-sown Phoenix Palm (Phoenix canariensis) standing partially within the NZTA designation. The trees are mostly healthy, except for one or two that are either senescent or dead. The trees as a group have considerable visual bulk. The trees stand at the top of a retained bank, but may be affected by SUP construction along SH18. Removal of these trees will result in some noticeable amenity losses. The bank on which the trees stand should be retained if possible. The same



largely applies to all mass plantings along the southern side of SH18 where the SUP is proposed. Refer also to 5.2.4 of the main report.

6.21 4 x small Pohutukawa up to 3 x 2m standing north of SH18. The trees are small and widelyspaced and have little amenity value. They will be removed to allow road widening and excavation to the north of SH18.

Sheet 7

No commentary on Sheet 7 as no works are proposed adjacent to any of the plantings surveyed.

Sheet 8

- 8.1 Row of about 20 Kanuka trees up to 5 x 5m in size. Variable in health, with about six senescent or dead. These trees provide valuable screening south of the road. The works layout suggests that some trees may be affected by SUP works adjacent. Parks may take an interest in these trees.
- 8.7 Group of about 130 trees, similar to 8.1, of which approximately half are Pohutukawa and half are Ngaio, with a few scattered individuals of other species such as Bottlebrush (*Callistemon sp*, Karo and Puka. The largest individuals are about 6m in height and spread. The density of this planting is highly variable. In places it provides considerable screening between SH18 and the adjacent houses. These trees appear to be affected by the excavations for the adjacent SUP and road widening works
- 8.10 Mixed native and exotic trees scattered along the route of the pipeline running north of SH18 and parallel to it. There are over 100 trees. Most trees are small and bush-like, up to 5 x 5 in size, whilst the largest are up to 8 x 8 in size. Native species include Totara, Kahikatea, Rimu, small Kauri, Kanuka and Ti Kouka. Natives make up the majority of the trees. There are also Black Wattle trees, an English Oak and five large Corsican Pines (*Pinus pinaster*). The pines are all mature to post-mature and are up to 20m in height. The trees have moderate individual value. Most trees are scattered in the landscape and hidden from general view by intervening trees. There is no scope to retain any of these trees as the scope of roadwork construction in the area does not allow this.
- 8.11 Mixed native planting scattered in a grazed paddock. Species include Totara, Kanuka, and Pohutukawa. The trees are hidden from general view and have little amenity value. If the new proposed wetland is established as shown all of the trees will have to be removed to allow earthworks. See also 5.2.7 of the main report.
- 8.13 A group of 19 Hybrid Poplar of up to 12m in height as well as two small Liquidambar trees and two small Ginkgo trees about 4m tall. There is no scope to retain any of these trees as they stand within the roading footprint. The trees are scattered and have little arboricultural value as specimens or as groups.
- 8.14 A windrow of natives consisting of trees up to 6m tall. Only part of the row of trees is affected, at the southern end where it encroaches on the roading corridor. Species include Hohere, Ti Kouka, Mahoe and Pohutukawa. There is also some Privet which is a weed. The trees are of moderate arboricultural value but stand within the proposed roading envelope.

Sheet 9

9.1 Ngaio and Pohutukawa planting along SH18. About 20 trees in this section. Most in this section are Ngaio, and the largest trees are about 6 x 6m. It appears that some of these trees may be directly or indirectly affected by road widening and associated engineering. Although





these are not high-quality trees they do provide some screening. Refer also to 5.2.4 of the main report.

- 9.2 This planting consists of six hybrid Poplar, a Pin Oak, a Wild Date Palm (*Phoenix reclinata*), a Pin Oak and a Pohutukawa standing in Rook Reserve. The largest trees are the Poplars at 14 x 6m. This planting has moderate amenity, but it appears that if will all have to be removed if the new wetland is constructed here, due to the amount of earthworks required. See also 5.2.8 of the main report.
- 9.5 An area of mixed planting on the bank above SH18. Consists of Karamu, Puka, Harakeke and Brazilian Pepper (*Schinus terebinthifolius*) the latter is a weed. This area falls outside the NZTA designation but does not appear to be affected by works.
- 9.6 Road berm planting at the approach to Unsworth Drive, consisting of small native trees of up to 4 x 4m in size, comprising Ti Kouka, Pohutukawa, Ngaio and similar small roadside trees. It does not appear that significant alterations are proposed at this stage.
- 9.14 A small area of Kanuka planted at the end of William Pickering Drive. A SUP connection is proposed here, which will probably require the removal of Kanuka trees standing within the path alignment.

Sheet 10

- 10.1 This mass planting of Kanuka is on the southern bank of the westbound Albany Highway offramp from SH18. The trees are healthy and about 3 x 3m and in places form a continuous canopy. Some of the trees south of the road may be affected by road widening. Some of this vegetation is located in Bluebird Reserve which is described in 4.9 of the main report.
- 10.2 The road islands in the vicinity of Albany Highway are mass planted with a mix of natives with Kanuka dominant. The individual bushes / trees are up to 3 x 3m in size. Species encountered include Kanuka, Akeake, Puriri, Koromiko, Ti Kouka, and Taupata. Some trees in this group will be removed to allow construction of the SUP along the northern edge of the motorway.








Appendix D Site Photographs















Site photographs are provided, as numbered in the site photograph column of **Appendix B**. Not every site was photographed, and some photographs cover a number of trees or groups of trees. Please refer to Appendix A for the locations of trees, and Appendix B for numbering and other details.



Fig 1.1 Motorway planting north of Oteha

Fig 1.2 Motorway planting – north of Oteha, northbound









Fig 1.3 Motorway planting at Lucas Creek bridge



Fig 1.4 Flax / Ti Kouka at Oteha Valley Road SW pond









Fig 1.5 Black Wattle – Oteha, southbound



Fig 1.7 Conifer windrow



Fig 1.10 Planting at Albany bus station









Fig 1.12 Planting, Albany bus station



Fig 2.2 Pond planting McClymonts Road



Fig 2.5 Kohuhu hedge McClymonts









Fig 2.6 Macrocarpa and Black Wattle - McClymonts



Fig 2.7 Kohuhu / mixed native planting – McClymonts busway on-ramp



Fig 2.12 Pines W of motorway, McClymonts







Fig 3.5 Roadside planting S of Greville Road



Fig 3.6 Roadside planting S of Greville










Fig 3.7 Roadside planting S of Greville



Fig 3.9 Isolated natives, NW of Albany Highway



Fig 3.10 Slash Pine, NW of Albany Highway





Fig 4.2 (foreground) and 4.3 Planting at Rosedale landfill



Fig 4.5 Planting at Rosedale landfill









Fig 4.6 SUP ramp location, Rosedale Road



Fig 4.10-4.11 Poplar trees along drainage easement



Fig 4.12 Harakeke mass planting, Rosedale Road









Fig 5.3 Roadside Ti Kouka, Rosedale WWTP southbound



Fig 5.4 Queen Palms, Rosedale WWTP southbound



Fig 5.5 Ti Kouka Rosedale WWTP southbound



Fig 5.7 Private planting Cowley Place adjacent motorway northbound









Fig 5.8 Ti Kouka roadside planting, Rosedale WWTP northbound



Fig 5.9 Queen Palm roadside planting, Rosedale WWTP northbound



Fig 5.10 Mixed natives and Queen Palms, Rosedale WWTP northbound



Fig 5.12 Kanuka - Rosedale South Park northbound on SH1







Fig 6.1 – 6.4 Ngaio / Pohutukawa / Kanuka – Constellation approach southbound



Fig 6.9 Natives / Queen Palm – Constellation bus station southbound



Fig 6.11 Flax planting, centre median



Fig 6.12 Washingtonia Palms, Constellation on-ramp southbound








Fig 6.14 Windrow between Rosedale South / Constellation Park and Rosedale WWTP




Fig 6.16 Flax, Washingtonia, Ngaio – Constellation on-ramp northbound



Fig 6.20 Kanuka S of SH18 westbound









Fig 8.1 SH18, south side Kanuka planting, westbound



Fig 8.4, 8.5, 8.6 SH18, Kanuka, Washingtonia, also Constellation Park / Rosedale South Park



Fig 8.7 Roadside planting W of Caribbean, SH18 westbound



Fig 8.9 Mixed native planting, Rosedale WWTP









Fig 8.10 Mixed planting, Rosedale WWTP looking north



Fig 8.12, 8.10 in background - Hybrid Poplar, Constellation Park at hockey pitches









Fig 8.13 Hybrid Poplar by SH18 eastbound



Fig 8.14 Native windrow, W boundary of Constellation Park









Fig 8.15 Washingtonia, SW of Constellation Park



Fig 8.15 Washingtonia Palms, Paul Matthews Road



Fig 9.1 Mixed native planting, SH18 westbound







Fig 9.2 Rook Reserve, SH18 westbound



Fig 9.3 Roadside Kanuka / Pohutukawa – Rook Reserve, SH18 westbound









Fig 9.4 Ti Kouka at Unsworth Drive Z service station



Fig 9.5 Mixed natives and exotics Unsworth Z Service Station









Fig 9.6 Mixed natives - Unsworth offramp, SH18 westbound



Fig 9.11 SW corner of Alexandra Creek reserve showing ramp location



Fig 9.12 Ti Kouka W of Alexandra Creek Reserve, SH18 eastbound



